

Daily Work History (by Work Location)

Period: 2/1/2013 - 2/28/2013

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Hill County

Precinct 1: County Roads

Location	Date	Work Done
Bierhalter Ln	2/7/2013	repaired fence
Canyon Ct between HCR 1300 and HCR 1450 S	2/13/2013	Trimmed brush or trees
Deep Canyon Dr between Deep Canyon Dr and Live Oak Dr	2/20/2013	Hauled materials for work crew picked up belly dump fromn the shop;returned to pct. Barn hauled 1 load of base to 1143
Fort Graham Rd N	2/1/2013	Bladed surface
HCR 1104 LP between HCR 1104 LP and HCR 1446	2/8/2013	Bladed surface
HCR 1125 between HCR 1130 S and HCR 1136	2/1/2013	Bladed surface
HCR 1137	2/5/2013	Hauled materials for work crew hauled 10 loads of base
	2/5/2013	Hauled materials for work crew
	2/6/2013	Hauled materials for work crew hauled 8 loads of base
HCR 1137 between HCR 1131 and HCR 1136	2/6/2013	Bladed surface; Added rock
HCR 1137 between HCR 1137 and HCR 1138	2/4/2013	Bladed surface; Added rock
	2/7/2013	Hauled materials for work crew hauled 7 loads of base to 1137;1 load to 1138
HCR 1138 between HCR 1137 and HCR 1212	2/7/2013	Bladed surface; Added rock
HCR 1138 between HCR 1138 and HCR 1250	2/8/2013	Hauled materials for work crew hauled 3 kloads of base to 1250;1 load to 1138
	2/8/2013	Hauled materials for work crew hauled 1 load of base to 1138; 3 loads to 1250
HCR 1145 LP	2/25/2013	Bladed surface; Added rock
	2/26/2013	Hauled materials for work crew hauled 4 loads of base
	2/27/2013	Hauled materials for work crew hauled 6 loads of base
	2/27/2013	Hauled materials for work crew hauled 6 loads of base
	2/27/2013	Hauled materials for work crew hauled 6 loads of base
	2/28/2013	Hauled materials for work crew hauled 6 loadfs of base

Daily Work History (by Work Location)

Period: 2/1/2013 - 2/28/2013

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Hill County

Precinct 1: County Roads

HCR 1145 LP	2/28/2013	Hauled materials for work crew hauled 3 loads of base;removed tree on Mobhon
	2/28/2013	Hauled materials for work crew hauled 6 loads of gravel
HCR 1212	2/1/2013	Overlaid road with asphalt hauled 5 loads of base
	2/1/2013	Hauled materials for work crew hauled 5 loads of base
	2/1/2013	Hauled materials for work crew hauled 4 loads of base
	2/1/2013	Bladed surface; Added rock
	2/4/2013	Hauled materials for work crew hauled 6 loads of base
	2/4/2013	Hauled materials for work crew hauled 2 loads of base
HCR 1212 between HCR 1137 and HCR 1212	2/5/2013	Hauled materials for work crew Hauled 1 load of base to 1212; 9 loads to 1137
HCR 1217 between HCR 1159 and HCR 1207	2/4/2013	Bladed surface; Added rock
HCR 1231	2/15/2013	Bladed surface
HCR 1240 between HCR 1240 and HCR 1248	2/25/2013	Patched road surface
	2/28/2013	Patched road surface
HCR 1250	2/11/2013	Hauled materials for work crew hauled 23 loads of base
	2/11/2013	Hauled materials for work crew hauled 3 loads;repaired wiper blades on truck
	2/13/2013	Bladed surface; Added rock
	2/14/2013	Bladed surface; Added rock
	2/14/2013	Hauled materials for work crew hauled 6 loads of base
	2/14/2013	Hauled materials for work crew hauled 4 loads of base;2 loads of pea gravel
	2/14/2013	Hauled materials for work crew hauled 4 loads of base
HCR 1250 between HCR 1236 and HCR 1239	2/14/2013	Bladed surface; Added rock
HCR 1250 between HCR 1240 and HCR 1263	2/8/2013	Bladed surface; Added rock
HCR 1260 between HCR 1262 and HCR 1223	2/4/2013	Bladed surface bladed HCR 1333

Daily Work History (by Work Location)

Period: 2/1/2013 - 2/28/2013

Work: All categories and types
 Location: All locations in all areas

All Assignments
 Hill County

Precinct 1: County Roads

HCR 1300 between HCR 1330 and HCR 1458	2/13/2013	Trimmed brush or trees cleared vbrush on Canyon;took truck to Aquilla for repairs
HCR 1350 W	2/19/2013	Hauled materials for work crew hauled 2 loaqds of base to 1350
	2/20/2013	Hauled materials for work crew hauled fill from 1350 to 1321
	2/20/2013	Hauled materials for work crew hauled fill from 1350 to 1321
	2/22/2013	Overlaid road with asphalt hauled fill rock to 1321;hauled 3 loads of base to 1350
HCR 1350 W between HCR 1458 and HCR 1350 W	2/22/2013	Hauled materials for work crew hauled 3 loads of base from Arnolds;hauled fikll diret to 1321
	2/22/2013	Hauled materials for work crew hauled 3 loads of base from Arnolds;hauled fikll diret to 1321
HCR 1355	2/13/2013	Bladed surface removed mud in front of XTO mud farm
HCR 1367	2/26/2013	Bladed surface; Added rock
HCR 1432 between HCR 1414 and HCR 1439	2/11/2013	Bladed surface
HCR 1439 between HCR 1300 and HCR 1217	2/8/2013	Bladed surface
HCR 1449 between HCR 1300 and HCR 1449	2/11/2013	Bladed surface
HCR 1458	2/14/2013	Bladed surface; Added rock
	2/15/2013	Hauled materials for work crew hauled 6 loads of base
	2/15/2013	Hauled materials for work crew hauled 5 loaqds of base
	2/22/2013	Hauled materials for work crew hauled 4 loads of base
	2/27/2013	Bladed surface; Added rock
HCR 1458 between HCR 1458 and HCR 1145 LP	2/25/2013	Hauled materials for work crew hauled 3 loads to 1458;1 load to 1145

County: Other Class: Other Type

Location	Date	Work Done
(location not on list)	2/19/2013	took belly dump to have windshiels repaired
Blum ISD Scool road	2/19/2013	Bladed surface interlocal agreement with City of Blum

Daily Work History (by Work Location)

Period: 2/1/2013 - 2/28/2013

Work: All categories and types

Location: All locations in all areas

All Assignments

Hill County

County: Other Class: Other Type

Pct 1 Barn	2/21/2013	Worked at precinct barn
Pct. 1 barn	2/15/2013	Hauled materials for work crew hauled 2 loads of pea gravel
Shop	2/21/2013	Worked at precinct barn maintained equipment;cleaned shop